

Your INSPECTION REPORT

Vehicle Description:

Date of Inspection: 6/25/2014

Full VIN: 2 [REDACTED]

Year: 1969

Engine Cylinders: 8

Mileage: 31002

Make: PONTIAC

Engine Liters: 6.6

Transmission Type: Manual

Model: GTO

Engine Type: Gas

Inspection Area	Overall Rating
Body	Good
Glass	Good
Wipers	Fair
Tires & Wheels	Good
Interior Items	Good
Gauges	Good
Audio System	Good
Carpet & Upholstery	Good
Trunk	Good
Electrical System	Good
Under Hood	Fair
Road Test	Good
Additional Inspection Points	Good



Exterior

BODY

OVERALL RATING: GOOD

Front	Chip 1-3"	Rear	OK
Hood	OK	Roof	OK
Bumpers	Chip 1-3"	Trim	OK
Left front	OK	Right front	OK
Left rear	OK	Right rear	OK
Left doors	OK	Right doors	OK
Overall Condition of Paint	GOOD		

GLASS

OVERALL RATING: GOOD

Windshield	OK	Rear window	OK
Left front window	OK	Right front window	OK
Left rear window	OK	Right rear window	OK

TIRES AND WHEELS**OVERALL RATING: GOOD**

Condition of tires	GOOD
--------------------	------

Condition of wheels	GOOD
---------------------	------

Comments on Tires and Wheels:

THE TIRES AND WHEEL ARE IN GOOD CONDITION. THE FRONT TIRES HAVE 11/32 TREAD. HE LEFT REAR TIRE HAS 9/32 TREAD, AND THE RIGHT REAR TIRE HAS 8/32 TREAD REMAINING.

WIPERS**OVERALL RATING: FAIR**

Front wipers	OK
--------------	----

Front wiper blades	Need Repair
--------------------	-------------

Front windshield washer	Need Repair
-------------------------	-------------

Comments on Exterior:

THE FRONT BUMPER HAS SOME CRACKS AND CHIPS. THE LEFT DOOR IS RUSTED AT THE BOTTOM. THE RIGHT DOOR IS CHIPPED ON THE EDGE BY THE HANDLE. THE WASHERS ARE INOPERATIVE AND THE WIPER BLADES NEED TO BE REPLACED. THE WIPERS ARE FUNCTIONING.

Interior**INTERIOR ITEMS****OVERALL RATING: GOOD**

Glove box	Need Repair
-----------	-------------

A/C cooling performance	OK
-------------------------	----

Heater operation	OK
------------------	----

Hood release	OK
--------------	----

Cigarette lighter	OK
-------------------	----

Head rests	OK
------------	----

Door panels	OK
-------------	----

Dash pad	OK
----------	----

Vanity mirrors	NOT REPORTED
----------------	--------------

GAUGES**OVERALL RATING: GOOD**

Speedometer	OK
-------------	----

Tachometer	OK
------------	----

Temperature	OK
-------------	----

Oil pressure	OK
--------------	----

Amp meter	OK
-----------	----

AUDIO SYSTEM**OVERALL RATING: GOOD**

Radio	OK
-------	----

CARPET AND UPHOLSTERY**OVERALL RATING: GOOD**

Front seats	OK
-------------	----

Front carpeting	OK
-----------------	----

Headliner	OK
-----------	----

Rear seats	OK
------------	----

Rear carpeting	OK
----------------	----

TRUNK**OVERALL RATING: GOOD**

Carpeting	NOT REPORTED
Tools	OK
Jack	OK

Spare tire	OK
Floor pan	OK

ELECTRICAL SYSTEM

OVERALL RATING: GOOD

Head lights	OK
Tail lights	OK
Brake lights	OK
Parking lights	OK

Turn signals	OK
Electric windows	NOT REPORTED
Electric seats	NOT REPORTED

Comments on Electrical System:

THE ELECTRICAL AND LIGHTING SYSTEMS OPERATE AS DESIGNED

UNDER THE HOOD

OVERALL RATING: FAIR

Oil leaks	YES
Exhaust leaks	NO
Exhaust smoke	NO

Comments on Interior:

THE GLOVE BOX LATCH IS MISSING.

Road Test

ROAD TEST

OVERALL RATING: GOOD

Brake system - noise, vibration, effort	OK
Suspension - performance, noise, rough road test	OK
Idle	OK
Engine noise	OK
Acceleration	OK
Horn	OK
Wind noise	OK
Starting	OK

Steering effort - drifting right or left	OK
Transmission shift quality, smoothness, effort, slippage	OK
Engine operating temperature	OK
Transmission/Transaxle noise	OK
CV joint/Drive axle noise	OK
Parking brake operation	OK
Engine performance	OK

Comments on Road Test:

THERE WERE NO DRIVEABILITY OR PERFORMANCE CONCERNS. POWER STEERING LEAK AT PITTMAN ARM SEAL. THERE IS AN OIL LEAK AT THE FRONT OF THE OIL PAN.

Additional Inspection Points

ADDITIONAL INSPECTION POINTS**OVERALL RATING: GOOD**

Door handles	OK	Door locks	OK
Gas door	OK	Gas cap	OK
Grille	OK	Evidence of smoke odor	OK

Comments on Additional Inspection Points:

ADDITIONAL INSPECTION POINTS ARE GOOD IN CONDITION AND OPERATION.